

**SITE ASSESSMENT REPORT ADDENDUM III**

**FOR**

**CITY OF FORT LAUDERDALE FORMER TRASH TRANSFER STATION  
1901 NW 6<sup>TH</sup> STREET  
FORT LAUDERDALE, FLORIDA**

**Prepared For:**



**FLORIDA DEPARTMENT OF ENVIRONMENTAL PROTECTION  
400 North Congress Avenue  
West Palm Beach, FL**

**Prepared on Behalf of:**

**City of Fort Lauderdale  
100 North Andrews Avenue  
Fort Lauderdale, Florida**

**Prepared by:**



**Evans Environmental & Geosciences  
14505 Commerce Way, Suite 400  
Miami Lakes, Florida 33016  
(305) 374-8300**

**July 31, 2008  
Project No.: 2005-1783**



Evans Environmental & Geosciences, LLC

14505 Commerce Way, Suite 400  
Miami Lakes, Florida 33016  
Tel: (305) 374-8300  
Fax: (305) 374-9004

**Professional Certification**

**EE&G Project No. 2005-1783**

**Combined Report:** Site Assessment Report Addendum III (SARA III), dated July 31, 2008

**Applicable Regulation:** Chapter 62-780, Florida Administrative Code (FAC)

**Site:** Former CFL Trash Transfer Station, located at 1901 NW 6<sup>th</sup> Street, in Fort Lauderdale, Broward County, Florida


**Client:** City of Fort Lauderdale, 100 North Andrews Avenue, Fort Lauderdale, FL 33301

**Firm:** Evans Environmental & Geosciences, LLC (EE&G), 14505 Commerce Way, Suite 400, Miami Lakes, Florida 33016

---

***Professional Geologist Certification:***

I, Craig C. Clevenger, P.G. #1666, certify that I currently hold an active license in the state of Florida and am competent through education and experience to provide the geological consulting services documented in the aforementioned SARA III. I further certify that, in my professional judgment, this report meets the requirements of Chapter 62-780, FAC, and Chapter 492, F.S., and was prepared by me, with field work completed under my direction. Moreover, I certify that EE&G holds an active certificate of authorization #GB41 to provide geological services in the state of Florida.

 #1666  
\_\_\_\_\_  
Craig C. Clevenger, P.G.  
8/5/08  
\_\_\_\_\_  
Date

**CONTENTS**

**Professional Certification Statement ..... i**

<u>Section</u>	<u>Page</u>
<b>1.0 - INTRODUCTION .....</b>	<b>1</b>
1.1 SITE LOCATION AND SETTING .....	1
<b>2.0 – RESPONSE TO FDEP COMMENTS .....</b>	<b>2</b>
<b>3.0 – EXPANDED GROUNDWATER ASSESSMENT .....</b>	<b>7</b>
3.1 GROUNDWATER ASSESSMENT METHODOLOGY .....	7
3.2 GROUNDWATER ASSESSMENT FINDINGS .....	8
3.2.1 Primary Drinking Water Standard Constituents .....	8
3.2.2 Secondary Drinking Water Constituents .....	9
3.2.3 Site-Specific Groundwater Flow Assessment Results .....	11
<b>4.0 - SOURCE REMOVAL EVENT.....</b>	<b>12</b>
<b>5.0 - EXPANDED SOIL ASSESSMENT .....</b>	<b>16</b>
<b>6.0 - RECOMMENDATIONS .....</b>	<b>20</b>
6.1 SOIL ASSESSMENT & REMEDIATION PLAN.....	20
6.2 GROUNDWATER NATURAL ATTENUATION MONITORING PLAN.....	21
6.3 NO FURTHER ACTION WITH CONDITIONS PLAN.....	22

**FIGURES**

1	USGS Site Location Map
2	Site Area Map
3	Monitoring Well Location Map
4	Groundwater Results: Primary Drinking Water Constituents
5	Groundwater Results: Secondary Drinking Water Constituents
6	Groundwater Flow Map – July 10, 2008
7	Source Removal Map
8	Post-Source Removal Confirmation Results – Dioxins/Furans
9	Post-Source Removal Confirmation Results – Arsenic
10	Post-Source Removal Confirmation Results – Lead
11	Expanded SARA III Soil Sampling Location Map

**TABLES**

Table 1	Summary of Groundwater Results
Table 2	Site-Specific Groundwater Elevation Measurements
Table 3	Summary of Post-Source Removal Soil Results
Table 4	Post-Source Removal Dioxin/Furan Congener TEF Conversion Summary
Table 5	Post-Source Removal Benzo(a)Pyrene Congener TEF Conversion Summary
Table 6	Summary of Expanded SARA III Soil Results
Table 7	Expanded SARA III Soil Dioxin/Furan Congener TEF Conversion Summary
Table 8	Expanded SARA III Soil Benzo(a)Pyrene Congener TEF Conversion Summary

**TABLE OF CONTENTS – (cont.)****APPENDICES**

Appendix A	FDEP Correspondence – April 30, 2008
Appendix B	Monitoring Well Completion Reports
Appendix C	Groundwater Analytical Results
Appendix D	Well Elevation Surveyor Measurements
Appendix E	Source Removal Event Photographs
Appendix F	Enlarged Source Removal Maps
Appendix G	Soil Disposal Manifests
Appendix H	Air Monitoring Results
Appendix I	Post-Source Removal Confirmation Soil Analytical Results
Appendix J	Expanded SARA IIII Soil Analytical Results